

IBEW 477 Journeyman Tool List

Journeyman's Tool List - Clothing

Sec. 2.32. (a) Journeyman Shall provide themselves with the following tools:

- Pencil
- Knife
- Six Foot Rule or Tape (not to exceed 25 feet)
- Small Chain Wrench (2")
- Pliers - cutting
- Screwdrivers - not over 8"
 - *Spin Type Nut Drivers 3/16", 1/4", 9/32", 7/16", 3/8" & 1/2"(permissible, but not required)
- Center Punch
- Compass Saw or Key Hole Saw (permissible, but not required)
- Hacksaw Frame
- Hammer
- Level - small
- Plumb bob
- Cold Chisel
- Square .
- Pliers - Channellocks
- Long Nose Pliers
- Sta Con Pliers
- Voltage Tester - 600 volt capacity (wiggins type)
- Tool pouch and belt
- Tool Box
- Diagonal Pliers
- Welding Hood and Goggles (permissible, but not required)
- *Allen Wrenches (full set through 3/8", plus 1/2")
- *Taps, 6-32, 8-32, 10-24
- *Tap Drills and clearance
- *Miller type wire stripper
- 3/8" socket set up to 3/4"
- Protractor (permissible, but not required)

*These tools are to be replaced by the contractor when broken or worn beyond use.

(b) Cable splicers shall furnish only hand tools.

(c) Workman shall wear clothing which is in compliance with the job requirements and safety standards (OSHA).

(d) Journeymen shall ascertain that all tools are in good workable and safe condition and comply with State, Federal Safety Standards (OSHA).

Gloves - Compounds

Sec. 2.33. Gloves must be furnished by the Employer where employees are required to use compounds and/or grease for wire or hardware lubrication, etc.